OIPE
JUN 24 2003
PATENT & TRADEMARK OFFICE
JC48



FIG 1

OIPE
JUN 24 2003
PATENT & TRADEMARK OFFICE
JC48



FIG 2



FIG 3



FIG 4



FIG 5

PATENT & TRADEMARK OFFICE JUN 24 2003 OIPE JC48
JUN 24 2003 OIPE JC48 PATENT & TRADEMARK OFFICE



Six Measurements Obtained

Fa(high)	High
Fa (low)	Low
Fb(high)	
Fb(low)	

FIG 6

F high = Fa(high)/Fb(high)

F low = Fa(low)/Fb(low)

$t^* = [\ln (F\ high) - \ln (F\ low)]/(High - Low)$

FIG 7

MAP OF FRACTURED ZONE



FIG 8



PATENT & TRADEMARK OFFICE
JUN 24 2003
JC48




tx values
1.0
0.0
0.5
1.0
1.5
2.0
2.5
3.0
Feet
0
10,000
20,000
2,760,000
2,770,000
2,780,000
2,790,000
2,800,000
2,810,000
2,820,000
2,830,000
2,840,0
wintgrk_orig90
BEST AVAILABLE COPY

Fig 11

OIPE JCAB
JUN 24 2003
PATENT & TRADEMARK OFFICE



FIG. 11

BEST AVAILABLE COPY